

GREY SCALES, AATCC AND ISO

AATCC Gray Scale for Staining

KCT-3061

The Gray Scale for Staining is used to visually evaluate staining on Multifiber samples due to colorfastness tests as described in Evaluation Procedure 2 which is included in the purchase of Gray Scale for Staining.



ISO Gray Scale for Staining to ISO 105 - A03

KCT- 3062



AATCC Gray Scale for Color Change

KCT-3063

The Gray Scale for Color Change is used to visually evaluate change in color due to colorfastness tests as described in Evaluation Procedure 1 which is included in the purchase of Gray for Color Change.



ISO Gray Scale for Color Change to ISO 105 - A02

KCT-3064

